

4MP_Rainbow TL-340IPRN-36 ; DL-340IPRN-36
models **FW v5.0.1.0.27602_R.D. 20220126 release**

- solving the phenomenon with camera not sending some of the DDA alerts in some environments to the NVR although the camera recognized the event as expected
- Minor bug fixes.

Best Regards,

Provision-ISR support team